

Daily Work History (by Work Location)

Period: 5/1/2013 - 5/31/2013

Work: All categories and types  
 Location: All locations in all areas

All Assignments  
 Hill County

**Precinct 1: County Roads**

Location	Date	Work Done
HCR 1353 between HCR 1353 and HCR 1458	5/23/2013	Hauled materials for work crew hauled 2 loads of base to 1353; 3 load to 1458
	5/23/2013	Bladed surface; Added rock
HCR 1353 between HCR 1458 and HCR 1355	5/23/2013	Hauled materials for work crew hauled 2 loads of base to 1353;4 loads to 1458
Creek Dr	5/14/2013	Patched road surface
	5/14/2013	Patched road surface
	5/14/2013	Patched road surface
Park Ave	5/31/2013	Bladed surface; Added rock
	5/31/2013	Hauled materials for work crew hauled 1 load of base
Quarter Horse Rd	5/30/2013	Patched road surface
	5/30/2013	Patched road surface
	5/31/2013	Patched road surface Patched country club road
Quarter Horse Rd between Country Club Rd and Quarter Horse Rd	5/30/2013	Patched road surface
Quarter Horse Rd between Quarter Horse Rd and Country Club Rd	5/30/2013	Patched road surface
	5/30/2013	Patched road surface
HCR 1106 between HCR 1106 and HCR 1120	5/2/2013	Trimmed brush or trees
HCR 1106 between HCR 1114 and HCR 1106	5/21/2013	Cleared debris or fallen tree
HCR 1120	5/3/2013	Trimmed brush or trees
	5/3/2013	Trimmed brush or trees
	5/22/2013	Cleared debris or fallen tree cleared downed trees on 1106;1127;1443;1300
HCR 1120 between HCR 1120 and Creek Dr	5/6/2013	Patched road surface
	5/6/2013	Patched road surface
	5/6/2013	Patched road surface
HCR 1221	5/8/2013	Bladed surface; Pulled shoulders or ditches

Daily Work History (by Work Location)

Period: 5/1/2013 - 5/31/2013

Work: All categories and types  
 Location: All locations in all areas

All Assignments  
 Hill County

**Precinct 1: County Roads**

HCR 1227	5/1/2013	Hauled materials for work crew hauled 3 loads of base
	5/1/2013	Hauled materials for work crew hauled 4 loads of base
	5/1/2013	Hauled materials for work crew hauled 3 loads of rock
HCR 1227 between HCR 1221 and HCR 1248	5/1/2013	sprayed herbicide
HCR 1314 between Lakeview Dr W and HCR 1227	5/21/2013	Cleared debris or fallen tree
HCR 1319	5/29/2013	Hauled materials for work crew hauled 2 loads of over-sized rock and 2 loads of base
	5/29/2013	Bladed surface; Added rock
HCR 1433 between HCR 1433 and HCR 1434	5/13/2013	Hauled materials for work crew hauled 1 load of base to 1433; 3 loads to 1434; 4 loads to 1212
HCR 1433 between HCR 1434 and HCR 1433	5/13/2013	Bladed surface; Added rock
HCR 1434 between HCR 1429 and HCR 1424	5/17/2013	Trimmed brush or trees
HCR 1434 between HCR 1434 and HCR 1433	5/13/2013	Hauled materials for work crew hauled 2 loads of base to 1434; 2 loads to 1433; 2 loads to 1212
HCR 1443	5/24/2013	Trimmed brush or trees
HCR 1443 between HCR 1212 and HCR 1443	5/28/2013	Trimmed brush or trees hauled 3 loads of base to 1212
HCR 1450 S between HCR 1369 and HCR 1364	5/28/2013	Bladed surface; Pulled shoulders or ditches
HCR 1450 S between HCR 1369 and HCR 1367	5/28/2013	Bladed surface; Added rock

**County: Other Class: Other Type**

Location	Date	Work Done
(location not on list)	5/7/2013	maitenance on all of the diesel trucks
County barn	5/16/2013	Worked at precinct barn repaired truck lights, brakes and engine
HCR 1319	5/29/2013	Bladed surface; Added rock repaired large mud hole and graded entire road
Pct barn	5/9/2013	Worked at precinct barn serviced Mac # 16 & 17

Daily Work History (by Work Location)

Period: 5/1/2013 - 5/31/2013

Work: All categories and types  
 Location: All locations in all areas

All Assignments  
 Hill County

**County: Other Class: Other Type**

Pct.1 barn	5/8/2013	Worked at precinct barn serviced equipment
	5/8/2013	Worked at precinct barn serviced belly dump trucks
precinct 1 barn	5/8/2013	Worked at precinct barn serviced patch machine;picked up load of P2;serviced Mac #11
Shop	5/2/2013	Worked at precinct barn worked on trucks;removed fuel tanks and prepared for sale
streets of Blum	5/16/2013	Bladed surface Inter-local agreement with city of Blum to grade roads