

Daily Work History (by Work Location)

Period: 5/1/2015 - 5/31/2015

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Hill County

Precinct 1: County Roads

| Location | Date | Work Done |
|--|-----------|--|
| County Barn | 5/4/2015 | Worked at precinct barn repaired axel on Volvo dump truck |
| | 5/7/2015 | Worked at precinct barn repaired equipment;dumped preloaded road base; 1 load on 1306 & 1 load on 1311 |
| Crowfoot Ln | 5/15/2015 | Cleared debris or fallen tree |
| Crowfoot Ln between B Ave and Hilltop removed trees from warf,HCR 1248, | 5/14/2015 | Cleared debris or fallen tree |
| Crowfoot Ln between Crowfoot Ln and Timberline Dr | 5/20/2015 | Cleared debris or fallen tree reoved trees due to storm damage |
| Crowfoot Ln between Kennedy Dr and Ward Ln | 5/15/2015 | Cleared debris or fallen tree cleared fsalen trees due to storm damage |
| Crowfoot Ln between Ward Ln and Kennedy Dr | 5/15/2015 | Cleared debris or fallen tree downed trees due to storm damage |
| D Ave between D Ave and Ward Ln trimmed trees on Timberline,Hilltop | 5/14/2015 | Cleared debris or fallen tree |
| D Ave between Timberline Dr and Ward Ln cleared trees from Hilltop, | 5/14/2015 | Trimmed brush or trees |
| Juniper Cove Rd between HCR 1425 and HCR 1369 hauled 1 load of over-sized rock to 1425-due to storm damage | 5/20/2015 | Hauled materials for work crew removed downed trees from the roadway due to storm damage |
| Juniper Cove Rd between Juniper Cove Rd and HCR 1425 repaired washout due to storm | 5/20/2015 | Cleared debris or fallen tree |
| Koller Dr between Palomino Lp and Valasta St cleared trees on 1256,1314,Quarterhorse,Kennedy | 5/11/2015 | Cleared debris or fallen tree |
| Lakeshore Tr added over-sized rock to Cedar Avenue | 5/29/2015 | Cleared debris or fallen tree |
| Lakeshore Tr between Cedar St /LOR and HCR 1363 | 5/29/2015 | Cleared debris or fallen tree |
| Pinto Ridge between Palomino Lp and Appaloosa St removed trees from roadway | 5/19/2015 | Cleared debris or fallen tree removed trees and brush from roadways due to storms |
| Pinto Ridge removed downed trees on 1303,1256,Valdesta,Palamino loop,1212,1206,Quarterhorse, | 5/11/2015 | Cleared debris or fallen tree |
| Quarter Horse Rd between Country Club Rd and Quarter Horse Rd | 5/29/2015 | Cleared debris or fallen tree |

Daily Work History (by Work Location)

Period: 5/1/2015 - 5/31/2015

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Hill County

Precinct 1: County Roads

| | | |
|---|-----------|---|
| Ward Ln between HCR 1418 and Ward Ln cleared downed trees due to storm damage | 5/14/2015 | Cleared debris or fallen tree |
| Washita Tr | 5/19/2015 | Cleared debris or fallen tree removed downed trees due to storm damage |
| | 5/19/2015 | Cleared debris or fallen tree result of storm damage |
| | 5/19/2015 | Cleared debris or fallen tree |
| Washita Tr between Washita Tr and Hillside Dr REMOVED A LARGE TREE FROM THE ROADWAY | 5/19/2015 | Cleared debris or fallen tree storm damage the cause of downed trees |
| | 5/19/2015 | Cleared debris or fallen tree |
| Washita Tr between Washita Tr and Hillside Dr removedsa large tree on the roadway | 5/19/2015 | Cleared debris or fallen tree |
| HCR 1120 | 5/8/2015 | Cleared debris or fallen tree |
| HCR 1120 between HCR 1120 and HCR 1130 N | 5/6/2015 | Bladed surface; Added rock |
| HCR 1127 | 5/4/2015 | Worked at precinct barn repaired Volvo dump truck;had to order parts for universal joints |
| | 5/4/2015 | Worked at precinct barn repaired Volvo dump truck;had to order parts for universal joints |
| | 5/5/2015 | Worked at precinct barn replaced batteries on # 11 trator; had truck and trailer inspected;repaired a flat on trailer |
| | 5/8/2015 | Worked at precinct barn loaded used tires in the recycling trailer |
| HCR 1136 between HCR 1136 and HCR 1106 | 5/7/2015 | Bladed surface; Added rock |
| HCR 1137 | 5/5/2015 | Bladed surface; Added rock |
| | 5/5/2015 | Hauled materials for work crew |
| | 5/5/2015 | Hauled materials for work crew hauled 3 loads of base to 1137; pre-loaded one load |
| HCR 1137 hauled 3 loads of base | 5/4/2015 | Hauled materials for work crew repairede Volvo dump truck |
| HCR 1137 hauled 4 loads of base; 1 preload | 5/5/2015 | Hauled materials for work crew had truck and ttrailer inspected |
| HCR 1145 LP | 5/13/2015 | used ditching machine to clear the ditch |

Daily Work History (by Work Location)

Period: 5/1/2015 - 5/31/2015

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Hill County

Precinct 1: County Roads

| | | |
|--|-----------|--|
| HCR 1145 LP | 5/13/2015 | cleared ditch with new ditch machine |
| HCR 1212 | 5/21/2015 | Patched road surface put over-sized rock in washed areas |
| HCR 1221 | 5/1/2015 | Hauled materials for work crew hauled 5 loads of base to 1221 |
| HCR 1221 between HCR 1217 and HCR 1227 removed numerous trees from many roads in pct 1 | 5/11/2015 | Cleared debris or fallen tree removed trees and brush due to storm damage. |
| HCR 1221 removed downed trees on 1227,1221,Pinto ridge,Koller,1256 | 5/11/2015 | Cleared debris or fallen tree |
| HCR 1227 between HCR 1227 and HCR 1221 | 5/1/2015 | Bladed surface; Added rock |
| HCR 1227 between HCR 1227 and HCR 1365 removed treesw from roadways | 5/28/2015 | Cleared debris or fallen tree |
| HCR 1231 between HCR 1102 and HCR 1104 LP removed trees and brush from the roadwa | 5/13/2015 | Cleared debris or fallen tree removed trees and brush from the roads due to the storm damage |
| HCR 1231 between HCR 1230 and HCR 1231 put over-sized rock in washed areas | 5/27/2015 | Patched road surface removed trees from roadways due to storm damage |
| HCR 1236 | 5/1/2015 | Patched road surface |
| | 5/1/2015 | Patched road surface |
| | 5/16/2015 | Cleared debris or fallen tree repaired a large sink hole on 1236;removed trees from the road way |
| HCR 1240 closed numerous roads due to flooding and tornadoes | 5/10/2015 | Other work |
| HCR 1256 | 5/13/2015 | Trimmed brush or trees |
| HCR 1256 between HCR 1314 and HCR 1231 removed trees and brush from roadways | 5/12/2015 | Cleared debris or fallen tree |
| HCR 1256 cleared trees on 1256,Pinto ridge,1314,1221 | 5/11/2015 | Cleared debris or fallen tree |
| HCR 1300 between HCR 1300 and HCR 1313 cleared downed trees on 1364,1331 | 5/12/2015 | Cleared debris or fallen tree |
| HCR 1300 between HCR 1300 and HCR 1313 cleared trees from road on 1331 | 5/12/2015 | Cleared debris or fallen tree |

Daily Work History (by Work Location)

Period: 5/1/2015 - 5/31/2015

Work: All categories and types

All Assignments

Location: All locations in all areas

Hill County

Precinct 1: County Roads

| | | |
|---|-----------|---|
| HCR 1300 between HCR 1300 and HCR 1331 HCR 1364,1313 | 5/12/2015 | Cleared debris or fallen tree |
| HCR 1303 between HCR 1123 and HCR 1136 | 5/12/2015 | Cleared debris or fallen tree |
| HCR 1306 between HCR 1306 and HCR 1311 | 5/7/2015 | Bladed surface; Added rock |
| HCR 1311 between HCR 1311 and HCR 1306 | 5/7/2015 | Hauled materials for work crew hauled 1 load of base to 1311 & 1 load to 1306 |
| HCR 1313 between HCR 1313 and HCR 1305 | 5/5/2015 | Bladed surface; Added rock |
| HCR 1314 between HCR 1314 and HCR 1306 | 5/6/2015 | Bladed surface; Added rock |
| HCR 1314 hauled a load of base to 1314;cleared trees from Brazos,Creekview aand 1104 | 5/7/2015 | Hauled materials for work crew |
| HCR 1363 between Lakeshore Tr and Cedar St /LOR dropped 1 load of over-size rock on Cedar | 5/29/2015 | Hauled materials for work crew Cleared fallen trees on Lakeshore |
| HCR 1364 | 5/21/2015 | Cleared debris or fallen tree all due to storm damage |
| HCR 1364 between HCR 1364 and Chicasha Tr | 5/21/2015 | Cleared debris or fallen tree all due to storm damage |
| HCR 1364 between HCR 1364 and Chicasha Tr cleared brush from roadways and ditches | 5/21/2015 | Cleared debris or fallen tree |
| HCR 1364 between HCR 1367 and HCR 1364 hauled 4 loads of over-sized rock to 1364, damage due to storm | 5/28/2015 | Hauled materials for work crew |
| HCR 1364 hauled 3 loads of over-sized rock to 1364--due to storm damaghe | 5/28/2015 | Hauled materials for work crew |
| HCR 1364 hauled4 loads of over-sized rock to 1364--due to storm damage | 5/28/2015 | Hauled materials for work crew |
| HCR 1367 between HCR 1361 and HCR 1364 remove3d trees;put over-sized rock in washed areas | 5/22/2015 | Patched road surface removed trees off roads due to storm damage |
| HCR 1369 between HCR 1136 and HCR 1369 cleared brush and trees from roadway due to storm damage | 5/20/2015 | Cleared debris or fallen tree |
| HCR 1413 W | 5/6/2015 | Hauled materials for work crew hauled 1 load of base to 1413;removed trees from 1104 , Brazos & Creekview |

Daily Work History (by Work Location)

Period: 5/1/2015 - 5/31/2015

Work: All categories and types

All Assignments

Location: All locations in all areas

Hill County

Precinct 1: County Roads

| | | |
|--|-----------|--|
| HCR 1414 between HCR 1413 W and HCR 1414 hauled 1 load of over-sized rock to 1413; 2 loads to 1414 | 5/18/2015 | Hauled materials for work crew hauled rock due to storm damage |
| HCR 1414 between HCR 1414 and HCR 1439 | 5/27/2015 | Hauled materials for work crew hauled 6 loadfs of base on 1439,1414,1418 |
| HCR 1414 between HCR 1439 and HCR 1414 put over-sized rock in washed area | 5/26/2015 | Cleared debris or fallen tree cleared trees from road way due to storm damage |
| HCR 1418 | 5/14/2015 | Hauled materials for work crew helped remove trees from Crowfoot, Ward, |
| HCR 1418 between HCR 1418 and HCR 1413 W | 5/26/2015 | Bladed surface; Added rock placed over-sized rock intyo washed areas |
| HCR 1418 between HCR 1418 and HCR 1413 W 3 loads of over-sized rock on 1418 | 5/26/2015 | Hauled materials for work crew |
| HCR 1418 between HCR 1418 and HCR 1425 hauled 2 loads of over-sized rock to 1418;1 to 1425 | 5/18/2015 | Hauled materials for work crew |
| HCR 1418 between HCR 1418 and HCR 1425 hauled 3 loads of over-sized rock to 1418 | 5/18/2015 | Hauled materials for work crew |
| HCR 1418 between HCR 1418 and HCR 1425 removed trees from roadway;placed over-sized rock in washouts | 5/30/2015 | Cleared debris or fallen tree all work was due to heavy rains and storm damage |
| HCR 1425 between HCR 1413 W and HCR 1425 removed trees from roadways;repaired wsashout areas | 5/31/2015 | Cleared debris or fallen tree all work was done due to storm damage |
| HCR 1425 between HCR 1425 and HCR 1424 bladed 1429, filled in wash area | 5/27/2015 | Bladed surface; Added rock all of the work is a result of the storms of the past 2 weeks9May 10) |
| HCR 1425 between HCR 1425 and HCR 1429 cleared ditches on 1429 to allow drainage;cleared brush fron right of ways to facilitate drainage | 5/26/2015 | Bladed surface; Pulled shoulders or ditches |
| HCR 1425 between HCR 1425 and Juniper Cove Rd cleared brush on 1369,1145 | 5/20/2015 | Hauled materials for work crew hauled 1 load of over-sized rock to 1425 |
| HCR 1428 between HCR 1428 and HCR 1137 hauled 3 loads of base to 1428; 2 loads of base to 1137; pre load I load for 1137 | 5/4/2015 | Hauled materials for work crew |
| HCR 1428 between HCR 1428 and HCR 1429 | 5/4/2015 | Bladed surface; Added rock |

Daily Work History (by Work Location)

Period: 5/1/2015 - 5/31/2015

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Hill County

Precinct 1: County Roads

| | | |
|--|-----------|---|
| HCR 1429 hauled 6 loads of over-sized rock | 5/27/2015 | Hauled materials for work crew |
| HCR 1432 between HCR 1432 and HCR 1439 removed trees and brush from the road ways | 5/18/2015 | Cleared debris or fallen tree removed trees abnd brush from the road ways |
| HCR 1439 between HCR 1414 and HCR 1439 haulefd over-sized rock and road base to fill wahed out | 5/27/2015 | Hauled materials for work crew |
| HCR 1443 cleaned out clogged culverts on 1217,1443,1364 | 5/26/2015 | Cleaned out or fixed road culvert |