

Daily Work History (by Work Location)

Period: 10/1/2016 - 10/31/2016

Work: All categories and types  
 Location: All locations in all areas

All Assignments  
 Hill County

**Precinct 1: County Roads**

Location	Date	Work Done
Comanche Tr between Comanche Tr and HCR 1236	10/13/2016	Bladed surface; Pulled shoulders or ditches
County Barn	10/3/2016	Worked at precinct barn took truck to Lone Star Truck service for repairs;serviced #16
	10/3/2016	Worked at precinct barn
	10/3/2016	Worked at precinct barn constructed a welding table
	10/4/2016	Worked at precinct barn built welding table
	10/5/2016	Other work
	10/5/2016	attended 1/2 day conference on road maintainence;demonstrated MgCL application
	10/10/2016	Other road work
Giant Cedar Dr between Giant Cedar Dr and Waterview Dr	10/11/2016	Patched road surface
HCR 1102 between HCR 1102 and HCR 1104 LP	10/31/2016	Bladed surface; Pulled shoulders or ditches
	10/31/2016	Hauled materials for work crew
	10/31/2016	Hauled materials for work crew hauled 9 loads of base to 1102;2 loads of base to 1104
HCR 1114 between HCR 1114 and HCR 1106	10/11/2016	Bladed surface; Pulled shoulders or ditches
HCR 1120	10/13/2016	Bladed surface; Added rock
HCR 1120 between HCR 1120 and HCR 1123 graded 1130 N. and 1130 S.	10/10/2016	Bladed surface; Added rock
HCR 1120 between HCR 1120 and HCR 1123 Shredded 1114	10/5/2016	Trimmed brush or trees
HCR 1120 between HCR 1120 and HCR 1123 shredded 1121 & 1114	10/5/2016	Mowed grass
HCR 1127 between HCR 1127 and HCR 1130 N graded HCR 1130 S;Creekwood Drive,Bermuda,High Meadow	10/11/2016	Bladed surface; Added rock
HCR 1136	10/10/2016	Hauled materials for work crew hauled 5 loads of base
	10/10/2016	Hauled materials for work crew hauled 5 loads of base
	10/12/2016	Bladed surface; Added rock

Daily Work History (by Work Location)

Period: 10/1/2016 - 10/31/2016

Work: All categories and types  
 Location: All locations in all areas

All Assignments  
 Hill County

**Precinct 1: County Roads**

HCR 1136 between HCR 1136 and HCR 1313	10/11/2016	Hauled materials for work crew Hauled 3 loads of base to 1136; 4 loads to 1313
HCR 1195 between HCR 1195 and Creekwood Dr /CW	10/13/2016	Bladed surface; Added rock
HCR 1217	10/3/2016	Mowed grass mowwed around the shop
	10/3/2016	Trimmed brush or trees
HCR 1240	10/31/2016	Patched road surface Chip sealed parking lot at the Fair Grounds
	10/31/2016	Patched road surface
	10/31/2016	Patched road surface Drove distribution tyruck to chip seal parking lot at County fair Grounds
HCR 1245	10/26/2016	Hauled materials for work crew hauled 4 loads of rock from Pct.2
	10/26/2016	Laid oil base
	10/27/2016	Hauled materials for work crew hauled 4 loads of rock to chip seasl from pct.2
HCR 1245 between HCR 1245 and HCR 1248	10/27/2016	Hauled materials for work crew hauled 6 loads of gravel to chip sealer
HCR 1246	10/26/2016	Overlaid road with asphalt hauled 4 loads of pea gravel to HCR 1246 for chip seal
	10/26/2016	Laid tack oil
HCR 1248	10/4/2016	Patched road surface
	10/12/2016	comnpacted road surface;watered road
	10/12/2016	Bladed surface bladed and watered surface;prepare for chip seal
	10/17/2016	Hauled materials for work crew
	10/17/2016	Hauled materials for work crew hauled 4 loads of pea gravel to 1248 ;prepare to chip seal road
	10/17/2016	Bladed surface
	10/17/2016	Hauled materials for work crew
	10/17/2016	Hauled materials for work crew hauled 4 loads of pea gravel to 1248 for chip sealing
	10/18/2016	Hauled materials for work crew

Daily Work History (by Work Location)

Period: 10/1/2016 - 10/31/2016

Work: All categories and types  
 Location: All locations in all areas

All Assignments  
 Hill County

**Precinct 1: County Roads**

HCR 1248	10/18/2016	Overlaid road with asphalt hauled 5 loads of gravel to prepare for seal coating
	10/18/2016	Hauled materials for work crew
	10/18/2016	Hauled materials for work crew hauled 5 loads of pea gravel to prepare for seal coating
	10/18/2016	Mixed oil & dirt sprayed soil stablized on road surface
	10/18/2016	Bladed surface
	10/18/2016	Used pad foot roller to pack base material in preparation of chip sealing
	10/18/2016	Mixed oil & dirt
	10/18/2016	Mixed oil & dirt operated distribution truck to lay down basre stablizer
	10/18/2016	Hauled materials for work crew
	10/18/2016	Bladed surface bladed and watered surface to prepare for chip seal
	10/19/2016	Patched road surface hauled 2 loads of stablizer to 1248;repaired potholes
	10/19/2016	Hauled materials for work crew hauled 3 loads of pea gravel to prepare for chip sealing 1248
	10/19/2016	Bladed surface
	10/19/2016	Hauled materials for work crew
	10/19/2016	Hauled materials for work crew
	10/19/2016	Hauled materials for work crew hauled 2 lloads of gravel to 1248;1 load of gravel for pot hole patcher
	10/19/2016	Patched road surface
	10/19/2016	Bladed surface bladed,watered and roll surface to prepare for chip seal
	10/20/2016	Patched road surface
	10/20/2016	Bladed surface bladed and water surface prepoaring for chip seal
	10/20/2016	Patched road surface
	10/21/2016	Bladed surface; Added rock
	10/24/2016	Swept road surface preparong for chip sealing

Daily Work History (by Work Location)

Period: 10/1/2016 - 10/31/2016

Work: All categories and types  
 Location: All locations in all areas

All Assignments  
 Hill County

**Precinct 1: County Roads**

HCR 1248	10/24/2016	Laid oil base Drove distribution truck and sprayed tac oil
	10/24/2016	Hauled materials for work crew hauled 4 loads of pea gravel to stock pile for chip sealing
	10/24/2016	Hauled materials for work crew
	10/24/2016	Overlaid road with asphalt
	10/25/2016	Hauled materials for work crew
	10/25/2016	Overlaid road with asphalt operated chip spreader
	10/25/2016	Hauled materials for work crew
	10/25/2016	Hauled materials for work crew hauled 2 loads of gravel;haule graqvel to chip spreader
	10/25/2016	loaded trucks for chip seal
	10/25/2016	Hauled materials for work crew hauled 4 loads of pea gravel to stock pile for chip sealing
	10/25/2016	Hauled materials for work crew hauled2 loads of gravel;hauled gravel to chip spreader
	10/25/2016	Laid oil base
	10/25/2016	Hauled materials for work crew
	10/26/2016	Overlaid road with asphalt oprated chip spreader
	10/27/2016	Overlaid road with asphalt oprated chip spreader
	10/28/2016	Overlaid road with asphalt
	10/28/2016	Overlaid road with asphalt Operated ship spreader on 1248;seal coated road
	10/28/2016	Hauled materials for work crew
	10/28/2016	Hauled materials for work crew haulefd 2 loads of gravel to chip seal;hauled 4 loads to chip sealer
	10/28/2016	Overlaid road with asphalt
	10/28/2016	Hauled materials for work crew hauled 2 loads of gravel to chip seal;Hauled 4 loads to chip sealer
	10/28/2016	Overlaid road with asphalt operated distribution truck to seal coat 1248

Daily Work History (by Work Location)

Period: 10/1/2016 - 10/31/2016

Work: All categories and types

All Assignments

Location: All locations in all areas

Hill County

**Precinct 1: County Roads**

HCR 1248 between HCR 1248 and HCR 1245	10/27/2016	Overlaid road with asphalt distributed 4 loads of emulsion on 1248 & 1245
	10/27/2016	Hauled materials for work crew hauled gravel to chip sealer on 1248 & 45
HCR 1248 between HCR 1248 and HCR 1313	10/12/2016	Hauled materials for work crew hauled 2 loads of base to 1248; 2 loads to 1313
	10/12/2016	Hauled materials for work crew hauled 2 loads of base to 1248; 2 loads of base to HCR 1313
	10/12/2016	Hauled materials for work crew
HCR 1306 between HCR 1306 and HCR 1104 LP hauled base to 1248	10/4/2016	Hauled materials for work crew hauled 1 load of base to 1306; 1 load of base to 1104; 2 loads to 1248
	10/4/2016	Hauled materials for work crew
HCR 1306 between HCR 1306 and HCR 1248	10/4/2016	Hauled materials for work crew
	10/4/2016	Hauled materials for work crew hauled 1 load of base to 1306; 3 loads of base to 1248.
HCR 1313	10/3/2016	Patched road surface picked load of P2 in El Mont; picked up a load of gravel at Harmons; patched road surface
	10/3/2016	Patched road surface
	10/4/2016	Patched road surface
	10/4/2016	Patched road surface
	10/5/2016	Patched road surface attended a road stabilization demonstration
HCR 1313 patched potholes on Giant Cedar & Mohon Circle	10/11/2016	Hauled materials for work crew hauled 3 loads of base to HCR 1313
HCR 1361 between HCR 1361 and HCR 1364	10/31/2016	Trimmed brush or trees
HCR 1432	10/4/2016	Bladed surface; Added rock